		Jule	. (0	<del></del>								
Work Ord												
Item ID: Revision ID:	D4039-041			Accept				Setup	Start			
Item Name:	Fwd Bracket A	Assembly							Stop			
Start Date: Required Date: Reference:	5/26/2010 6/4/2010	Start Qty: 2.00 Req'd Qty: 2.00			Cust Item I Customer:	D:						
Approvals:	Process Pla	n. V	Date/0-3-20	Tooling	D			Run	Start			
rappiovais.	QC:	"'	Date:	_ SPC (Y/N):		ate:			Stop			
Sequence ID/ Work Center II	D	Operation Description		Set Up/ Run Hours	Tool ID	Tool # Plan Code	Accep Qty	t Rej Qty		Reject Number	Insp. Stamp	
Draw Nbr	Revi	ision Nbr	-									
D4039	Α											
				0.00			/	Ja	106	/20		
Small Fab Small Fab		<b>Memo</b> 1- Assen	nble lanyard to bracket as per o	0.00 dwg <sup>-</sup>						/-07		
			npleteness to step on W/O	0.00	6/07		(F)					
QC Quality Control	•	Memo		0.00				_				

120

Packaging Packaging

Memo

Identify as per dwg & Stock Location: 192

0.00

X2 BB 10/06/10

W/O:			18/4	ORK ORDER CHANG									
DATE	STEP	PRO	OCEDURE CHA		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector				
Part No	:	PAR #:	Fault Cate	gory:	_ NCR: Yes	No DQ	A:	Date:					
				sposition: QA: N/C Closed: Date:									
NCR:			WORK ORD	ER NON-CONFORMA	ANCE (NC	R)							
DATE	STEP	Description of NC		Corrective Action Section B  nitial Action Description Sign &				Approval	Approval				
	JIL!	Section A	Initial Chief Eng	Sign Date		Section C Chief Eng							
	<u> </u>												
<b>5</b>													
									:				
•													
,													

Work Ord Wednesday, Ma											Page 2
Item ID: Revision ID: Item Name:	D4039-041 Fwd Bracket	Accombly		Accept					Setup	Star Stop	
Start Date: Required Date Reference:	5/26/2010	Start Qty: 2.00 Req'd Qty: 2.00			Cust Item I Customer:	D:				Stop	
Approvals:	Process Pl	an:	Date:	Tooling: SPC (Y/N):		ıte:			Run	Start Stop	
Sequence ID/ Work Center I 130 QC Quality Control	D	Operation Description QC21- Final Inspection - Memo	Work Order Release	Set Up/ Run Hours 0.00	Tool ID	Tool#	Plan Code	Accept Qty	t Rej Qty		Reject Insp. Number Stamp  /06/10 H  W  10-6-10

	•												
W/O:			WORK ORDER CHANGES										
DATE	STEP	PRO	OCEDURE CHAI	NGE		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector			
						ļ	•						
						-	<del></del>						
										•			
Part No	:	PAR #:	Fault Cate	jory:	NCR:	Yes N	lo DQA	<b>\</b> :	Date:				
	Res	solution:	Disposition	:	QA: I	VC Clo	sed:		Date:				
NCR:			WORK ORDE	R NON-CONFORMA	MANCE (NCR)								
DATE	STEP	Description of NC					Approval	Approval					
DAIL	SILF	Section A	Initial Chief Eng	Action Description Chief Eng		Sign & Section C		Chief Eng	QC Inspector				
						-1							

#### **Picklist Print**

Wednesday, May 26, 2010 1:54:35 PM

Work Order ID: 59135

Parent Item:

D4039-041

Parent Item Name: Fwd Bracket Assembly

Comments:

IPP RevA: new issue DD 09.12.15 verified by:EC



**Start Date: 5/26/2010** 

Required Date: 6/4/2010

Start Oty. 2.00

	ue DD 09.12.15		1 0y.LC					Start Qty: 2.00		Require	d Qty: 2.00	
Component Item ID/ Replacement Item Name Item ID	Mfg/ Purch		Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Stat Issued	us
04039-1 	Manufactured	No			B59	Each (37)	0.0000		25	0/06,	109	
02690-6 	Manufactured	No			100	Each	32.0000		2/5/	0/06	109	-+
			Location		Loc (	<u>Oty</u>	Loc Code			-		
			ST021	50005		32		-	7			
ELRS-010 ip Pin	Purchased	No		58375	100	32 Each	37.0000		2 E/S.	2/66	/69	•
			Location		Loc C	<u>Oty</u>	Loc Code		/ /			
				112689 113779		37 17 20			2.			
fS27039-1-11 	Purchased	No			100	Each	81.0000		2/5/	o fa	5/09	
			Location		Loc C	<u>)ty</u>	Loc Code			/ /		
			ST291			81			<u> </u>			
			•	9662		81			$\prec$ —			

Page 1

W/O:			WORK ORDER CHANGES											
DATE	STEP	PRO	OCEDURE CHA	NGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector					
Part No		PAR #:												
	Resc	olution:						Date: _						
NCR:		•	WORK ORD	ER NON-CONFORM	ANCE (N	CR)								
DATE	STEP	Description of NC			tion B	Vei	ification	Annroval	Approval					
	SIEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sig Da	n& ∣ <sub>S</sub>	ection C	Approval Chief Eng	QC Inspector					
							· · · · · · · · · · · · · · · · · · ·							
									<u> </u>					

#### **Picklist Print**

Wednesday, May 26, 2010 1:54:35 PM

Work Order ID: 59135

Parent Item: D4039-041

Parent Item Name: Fwd Bracket Assembly

**Comments:** 

IPP RevA: new issue DD 09.12.15 verified by:EC



Start Date: 5/26/2010

Required Date: 6/4/2010

Page 2

Start Qty: 2.00

Required Qty: 2.00

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Primary Item Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
MS21042L3	NISKI ASA KIKI KEAN	Purchased	No		100	Each	1,710.000	1	30 -			-

Nut

Location	Loc Oty	Loc Code
ST300	1710	
113537	20	
113644	190	
114523	1000	
114718	500	

NAS1149D0363J

Purchased

No

100

Each 674.0000


Washer

<b>Location</b>	Loc Qty	Loc Coc
ST298	674	
113288	2	
114292	672	


	•													
W/O:			WORK ORDER CHANGES											
DATE	STEP	PRO	DCEDURE CHA	NGE			Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector			
				,										
Part No	:	PAR #:	Fault Cate	gory:		_ NCI	R: Yes	No DQ	<b>A</b> :	Date:				
		esolution:												
NCR:			WORK ORDI											
DATE	STEP	Description of NC						Verific	ation	Approval	Approval			
		Section A	Initial Action Descr Chief Eng Chief Eng			cription Sign & Date			on C	Chief Eng	QC Inspector			
				·										
									:					
		· · · · · · · · · · · · · · · · · · ·							14					
		·												
						·		-		-				
									·					

ITEM NO.	QTY,	QTY.	7	6 5		3	2	<u> </u>	1 ]
	-041	QTY. -043	PART NUMBER	DESCRIPTION					1
1	Х		D4039-041	FWD BRACKET ASSEMBLY					i
2		×	D4039-043	AFT BRACKET ASSEMBLY					
3	1		D4039-1	FWD BRACKET					
4		1	D4039-3	AFT BRACKET					
5	1	1	D2690-6	LANYARD					
6	1	11	BLRS-010	PIP PIN					
7	1	1	MS27039-1-11	SCREW					
8	11	1	MS21042L3	NUT					
. 9	3	3	NAS1149D0363J	WASHER					
	6		3 3		(a)	Order	DART		
				5 6 8 9	SHOP ( RETURI  RETURI  ENGINER  UNCONTROL  SUBJECT TO AN  WITHOUT N  WORK OF  NO. 59/	N TO ERING LED COPY MENDMENT	7 8. 9 BRACKET ASSEM	5 DELEA COMPANY	6 S E I
			D4039-041 FWD BRACKE	T ASSEMBLÝ	2/10-5-24	D4039-043 AF I	ISSUE ASSEM	BLY   2010 -04	09.12.14

W/O:		WORK ORDER CHANGES											
DATE	STEP	PRO	OCEDURE CHAI	NGE		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector			
				-			-						
Part No	•	PAR #:	Fault Cate	gory:	NCR	: Yes	Vo DQ	A:	Date:				
	Re	esolution:	Disposition	1:	QA:	N/C Cld	sed:		Date: _	<del></del>			
NCR:			WORK ORDE	R NON-CONFORM	ANCE	(NCR	)		· · · · · · · · · · · · · · · · · · ·				
DATE	STEP	Description of NC		tion B		Verific	ation	,	Approval				
	J.L.	Section A	Initial Chief Eng	Action Description Chief Eng		Sign & Date	Secti		Chief Eng	QC Inspector			
				,									
					•								
					-								
	1		1		1					-			



W/O:		WORK ORDER CHANGES											
DATE	STEP	PROCEDURE CHANGE				Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector				
Part No:		PAR #:	Fault Category: N			CR: Yes No DQA: Date:							
	Res	solution:	Dispositio	n:	_ QA: N/C	A: N/C Closed: Date:							
NCR:			WORK ORD	ER NON-CONFORMA	NCE (NC	R)							
DATE	STEP	Description of NC Section A	Corrective Action Section B Initial Action Description			Verification		Approval	Approval				
			Chief Eng	Action Description Chief Eng		Sign & Section C		Chief Eng	QC Inspector				



W/O:		WORK ORDER CHANGES											
DATE STEP		PROCEDURE CHANGE			Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector				
					NCR: Yes No DQA: Date:								
	Resc	olution:	Disposition	:	_ QA: N/C	Closed:	Date:						
NCR:		1	WORK ORDE	R NON-CONFORM	ANCE (NC	R)							
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification		n Approval	Approval				
	0.2.		Initial Chief Eng	Action Description Chief Eng	Sigr Dat		tion C	Chief Eng	QC Inspector				
					:								
7													
							-						